


EASA	NOTIFICATION OF A PROPOSAL TO ISSUE AN AIRWORTHINESS DIRECTIVE	
	<p>PAD No.: 10-082</p> <p>Date: 10 August 2010</p> <p>Note: This Proposed Airworthiness Directive (PAD) is issued by EASA, acting in accordance with Regulation (EC) No 216/2008 on behalf of the European Community, its Member States and of the European third countries that participate in the activities of EASA under Article 66 of that Regulation.</p>	
<p>In accordance with the EASA Continuing Airworthiness Procedures, the Executive Director is proposing the issuance of an EASA Airworthiness Directive (AD), applicable to the aeronautical product(s) identified below. All interested persons may send their comments, referencing the PAD Number above, to the e-mail address specified in the 'Remarks' section, prior to the consultation closing date indicated.</p>		
Type Approval Holder's Name :		Type/Model designation(s) :
Dittel Messtechnik GmbH		FSG 2T VHF/AM Airband Transceivers
ETSO Authorisation: EASA.21O.1304 (formerly Germany, LBA.O.10.911/103 JTSO)		
Foreign AD :	Not applicable	
Supersedure :	None	
ATA 23		
Communication – Very High Frequency (VHF/AM) Transceiver – Modification		
Manufacturer(s):	Dittel Messtechnik GmbH, formerly Walter Dittel GmbH, Luftfahrtgerätebau	
Applicability:	<p>FSG 2T VHF/AM Airband Transceivers, Part Number (P/N) F10350, serial numbers (s/n) 35(X)-05100 through 35(X)-06462 inclusive, except units marked with Mod-Index: SB 1.06, and s/n 353-05172, 353-05189, 355-05557, 355-05696 and 356-05828.</p> <p>Note: (X) in the s/n prefix denotes any digit between 2 and 9, indentifying the year of manufacture (e.g. 2 = 2002, 3 = 2003, etc.).</p> <p>These radios are known to be installed on, but not limited to, aircraft certificated (validated) by EASA under CS 22, CS 23, CS-31HB, CS-VLA, and aircraft certificated (validated) prior to 28 September 2003 under equivalent National Standards by EU Member States or associated countries.</p>	
Reason:	<p>It was recently discovered that during production of certain FSG 2T transceivers, the transmitter capacitor C2038 was installed with wrong polarity.</p> <p>This condition, if not corrected, stresses the capacitor during transmit operation, possibly leading to:</p> <ul style="list-style-type: none"> • reduction of capacity, resulting in reduced signal modulation, which is observed by the receiver as a weak voice reception. • opening of the connection, leading to no audio transmission. • disintegration of the capacitor (at least one case has been observed). 	

	<p>The loss or reduction of function will not be detected by the pilot in any case.</p> <p>For the reasons described above, this AD requires the modification of the affected transceivers by replacing the capacitor with a new one, thereby correcting the polarity.</p>								
Effective Date:	[TBD: 14 days after final AD issue date]								
Required Action(s) and Compliance Time(s):	<p>Required as indicated, unless accomplished previously:</p> <p>(1) Within the time period specified in Table 1 of this AD, as applicable, modify the FSG 2T VHF/AM transceiver by replacing the capacitor C2038 with a new one, in accordance with the instructions of DITTEL Service Bulletin (SB) FSG2T-1.06.</p> <p style="text-align: center;">Table 1</p> <table border="1" style="margin-left: auto; margin-right: auto;"> <thead> <tr> <th>Affected FSG 2T s/n</th> <th>Compliance Time</th> </tr> </thead> <tbody> <tr> <td>35(X)-05100 through 35(X)-05550</td> <td>within 6 months after the effective date of this AD</td> </tr> <tr> <td>35(X)-05551 through 35(X)-06000</td> <td>within 12 months after the effective date of this AD</td> </tr> <tr> <td>35(X)-06001 through 35(X)-06462</td> <td>within 18 months after the effective date of this AD</td> </tr> </tbody> </table> <p>(2) After the effective date of this AD do not install any of the affected FSG 2T VHF/AM transceivers on an aircraft, unless it has been modified in accordance with the instructions of DITTEL SB FSG2T-1.06.</p>	Affected FSG 2T s/n	Compliance Time	35(X)-05100 through 35(X)-05550	within 6 months after the effective date of this AD	35(X)-05551 through 35(X)-06000	within 12 months after the effective date of this AD	35(X)-06001 through 35(X)-06462	within 18 months after the effective date of this AD
Affected FSG 2T s/n	Compliance Time								
35(X)-05100 through 35(X)-05550	within 6 months after the effective date of this AD								
35(X)-05551 through 35(X)-06000	within 12 months after the effective date of this AD								
35(X)-06001 through 35(X)-06462	within 18 months after the effective date of this AD								
Ref. Publications:	<p>DITTEL Service Bulletin SB FSG2T-1.06 dated 29 July 2010.</p> <p>The use of later approved revisions of this document is acceptable for compliance with the requirements of this AD.</p>								
Remarks :	<ol style="list-style-type: none"> 1. This Proposed AD will be closed for consultation on 07 September 2010. 2. Enquiries regarding this PAD should be referred to the Airworthiness Directives, Safety Management & Research Section, Certification Directorate, EASA. E-mail: ADs@easa.europa.eu. 3. For any question concerning the technical content of the requirements in this PAD, please contact: Dittel Messtechnik GmbH, www.dittel.com Sales/Service Department, Erpfinger Str. 36, D-86899 Landsberg, Germany, Telephone +49 8191 335 0, Fax +49 8191 335 149, E-mail service-funk@dittel.com. 								